

REPORT OF CHANNEL CONDITIONS (FOR CHANNELS 400 FEET WIDE OR GREATER) (EP 1130-2-520)						PAGE 1 OF PAGES		
TO: Navigation Interests						FROM: U.S. Army Engineer District, Baltimore P.O. Box 1715 Baltimore, Maryland 21203-1715		
RIVER/HARBOR NAME AND STATE Baltimore Harbor Baltimore, Maryland						MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Anchorage #4	19 Jun 2008	2475		35	15	15	17	17
REMARKS (Continue on reverse) All depths refer to MLLw for the 1983-2001 tidal epoch. This information represents the results of surveys made oin the dates indicated and can onlt be as indicating the results at that time. LQ=E1442975.52, N573698.16 (14.5') LIQ=E1443446.55, N573306.68 (15.0') RIQ=E1443477.41, N572134.90 (16.6') RQ=E1443433.24, N571698.52 (17.3')								